

CASE STUDY

**GS Technik
Jistebnice – Czech Republic**

Problem:

This firm made equipment of kitchens or dining rooms. These products are made by stainless steel. They have been sanding these products and a lot of dangerous dust have been generating by the process. They wanted to improve our workplace.



Solution:

We offered him Filtermax 3000 with arm Original.

Capture at Source